

## City of San Leandro Crosswalk Scoring Sheet

**Crosswalk Location:** Bancroft Ave and Oakes Blvd  
**Total Score:** 16  
**Prepared by:** Dean Hsiao  
**Date:** 10/26/2016

Criteria		Value	Score	Comments
A. School		None	0	
B. Roadway Cross Section	through lanes	2	6	2 through lanes with bike lane and parking
	center turn lane or median	No		
	bike lane and/or parking	Yes		
C. Posted Speed Limit or 85th Percentile Speed		30 mph	4	
D. ADT - Average Weekday Daily Traffic		10,000 to 15,000 vpd	3	10,400 vpd
E. Accident History (pedestrian/bike) within crossing location in past 3 years		0 accident	0	
F. Accident History (vehicle) - 5 or more rear end collision in past 3 years associated with activity from the crossing		No	0	one head-on collision
G. Traffic Signal or existing marked crosswalk located within 500 feet of subject review location		Yes	-5	290 feet to Bancroft/Dutton
H. Crossing roadway classification		Minor Arterial	3	
I. Coordination. Project can be coordinated with another Capital Improvement Project, Grant Opportunity, Development, or Overlay project for efficiency in design and construction and reduced resource demand.		No	0	
J. Pedestrian Volume >= 20 peds in one peak hour		No	0	no ped counts

<p>K. Site Conditions. This category allows the professional to assign up to 10 points for site conditions which are unusual, such as a side trail connection, or roadway gradient, or other aspect that in the opinion of the professional elevate the subject crossing beyond typical consideration.</p>		0	0	
<p>L. Implementation. The site meets criteria for installation or enhancement, satisfies certain community goals, and can be implemented relatively simply with minimal costs, staff time, or other resources as determined by the Department.</p>		Yes	5	
<b>Total Score</b>			<b>16</b>	