

Scity of Leandro

Hillside Drive
Geological Hazard
Abatement District (GHAD)
Update

Facilities and Transportation Committee



OVERVIEW

HISTORY

STATUS

NEXT STEPS

HILLSIDE DRIVE GHAD

A GHAD is a public agency, formed by a community to provide a management structure to address landslides, erosion, and other hazards

Hillside Drive GHAD - 26 parcels



HISTORY / TIMELINE



Feb 1998

El Nino Storms Cause Hillside Drive Landslide



2002

Hillside Drive Slope Stabilization Project Completed

GHAD Formation

GHAD accepts FEMA grant funds to repair of storm damage


Nov 2000


2022 Winter Storm

City clears debris and installs tarp to protect slope slide

Work exhausts remaining funds

Winter 2022






2022-23 Winter Storm



HSD1 - Slope above 2112 & 2126 (vacant lot) Hillside Dr HSD2 - Slope above 2150 Hillside Dr

- Broken pipe repaired
- Drainage ditches cleared
- > Tarps installed

HILLSIDE DRIVE GHAD



STATUS


July
2024
SURVEY
POTENTIAL
DISSOLUTION

August
2023
SURVEY
POTENTIAL
ASSESSMENT

Winter 2022

FUNDS DEPLETED

NEXT STEPS



QUESTIONS

